ServiceInfo 4/2024

Vipiteno, October 2024

NEW RETROFIT - ADDITIONAL MAINTENANCE EQUIPMENT IN THE RETURN STATION

Dear Customers,

we are pleased to inform you that we have introduced a retrofit to ensure greater safety during maintenance activities at the return station. The change affects automatic lifts from the year 2022 and earlier, which are equipped with a fixed maintenance platform, i.e. one that does not follow the movement of the tensioning carriage or hydraulic cylinder rod.

Specifically, the modernisation includes:

- A lifeline to which the operator can hook to carry out maintenance along the station walkway (fig.1).
- An additional platform that provides the operator with easy access to the upper area of the return sheave (fig.2).
- Attachments on the return sheave frame for access to the sheave support area, using a simple ladder (fig.3, fig.4).







OUR CUSTOMER SERVICE HOTLINE Available 365 days / 24 hours

ServiceInfo 4/2024







Fig.4

The proposal was born to facilitate the daily and monthly control/maintenance operations, allowing the technician to quickly and safely carry out the various activities foreseen in the return sheave area, avoiding the use of ladders that are not adequately fixed or scaffolding that often cannot be easily positioned.

The modernisation has already been carried out on some installations and the application includes the supply of all the necessary material, which is installed in 2 working days by 2 specialised LEITNER technicians.

In order to foresee an installation on your lift, we invite you to contact the LEITNER Customer Service to start a dedicated feasibility study.

Your LEITNER Customer Service Team

